



Lakes Region ThermalScan
68 Heath Drive
Gilmanton Iron Works, NH 03837
603 366-1552
www.LRThermalScan.com

Energy Audit, Level 3

9 November, 2011



Prepared For: Town of Rye

Property Address: **10 Central Street
Rye, New Hampshire 03870**

Table of Contents

EXECUTIVE SUMMARY	3
OVERVIEW.....	4
BUILDING DIAGRAMS	5
BUILDING PICTURES	5
OBSERVATIONS & TEST DATA.....	6
BUILDING ENVELOPE AIR LEAKAGE TESTING	6
HEATING FUEL CONSUMPTION ANALYSIS	6
ESTIMATED HEATING CONSUMPTION BY BUILDING COMPONENT.....	6
ANNUAL ENERGY COSTS	7
BUILDING SHELL MEASUREMENTS AND RATIOS	7
ESTIMATED SAVINGS & ENVIRONMENTAL IMPACT	8
ANNUAL BUILDING ENERGY CONSUMPTION.....	8
HEATING FUEL CONSUMPTION.....	8
IMPROVEMENTS MODELED TO CALCULATE ESTIMATED ENERGY SAVINGS	8
COMPARISON OF IMPROVED BUILDING TO CURRENT BUILDING CONDITION	9
THERMAL BOUNDARY REPORT	11
MAIN ATTIC SPACES.....	11
ATTIC HATCHES.....	14
EXTERIOR WALLS	15
FOUNDATION WALLS	20
SLAB FLOORS.....	21
WINDOWS	22
EXTERIOR DOORS.....	23
AIR BARRIER / AIR LEAKAGE REPORT	24
SYSTEMS REPORT	25
HEATING SYSTEM ASSESSMENT	25
AIR CONDITIONING ASSESSMENT	26
AIR DUCT ASSESSMENT.....	26
DOMESTIC HOT WATER ASSESSMENT	27
MECHANICAL VENTILATION ASSESSMENT	27
OTHER IMPROVEMENTS, RECOMMENDATIONS & CONSIDERATIONS.....	28
HEALTH, SAFETY & BUILDING DURABILITY	29
SELECTED INFRARED IMAGES.....	30
SELECTED DIGITAL IMAGES.....	32

Executive Summary

This is an 1800's church that has been converted into a municipal building. A lighting audit had previously been accomplished with lighting improvements implemented. The Town's intent is to reduce heating and air conditioning fuel consumption by installing a geothermal system to replace the existing conditioning systems. The current systems have been inspected and a geothermal system designed to carry the current building loads. Due to the previous lighting audit and systems inspection, this report focuses primarily on the building's shell and air barrier to assess energy saving opportunities. A comparison of reported annual heating fuel consumption to data provided by the US Information Administration, for office buildings within the appropriate climatic zone, reveals that this building consumes **41.5%** more heating fuel per square foot of conditioned space than average. Not surprisingly the calculated heating season fuel consumption, if all recommended thermal boundary and air barrier improvements were implemented, reduces the expected fuel consumption by **53%**.

The building's air barrier was assessed using a dual fan calibrated blower door. Due to the metal ceiling in the main building section, the building was pressurized to +50 Pa with reference to the exterior for infiltration rate testing and then depressurized to -12 Pa for thermal imaging inspection. Air leakage tested at 10,980 CFM @ +50 Pa. This level of air leakage indicates that significant energy savings can be achieved through moderate air sealing efforts and cost. Infrared imaging and visual inspection was accomplished of the entire building shell. A significant percentage of the building's thermal boundary was found without insulation. Many building assemblies were found lacking a proper air barrier contributing significantly to the building's energy load due to excessive air exchange. It should be noted that if the recommended building shell improvements are implemented the size of the new geothermal system can be *significantly* and proportionately reduced to address the reduced heating and cooling loads with the improved thermal boundary and air barrier.

Energy modeling was conducted to simulate the building's expected fuel burn with the recommended improvements. The modeled improvements to the thermal boundary and air barrier include:

- 40% reduction in infiltration
- Insulating all wall and attic assemblies that are currently uninsulated
- Improving the insulated attics to achieve R50
- Adding R10 foundation / slab perimeter insulation to 2' below grade
- Insulating the Attic side walls with cavity insulation, plus R10 continuous insulation
- Improving the attic hatches to R40 weather-stripped hatches

The estimated cost of the thermal boundary and air barrier improvements noted in this report is \$27,500.00 with an expected annual energy savings of **\$4,365.00**. This provides a **15.8%** return on investment and a simple payback of **6.3** years. Additionally the reduced fuel burn would reduce carbon dioxide emissions by **14.3** tons annually. The slab and foundation wall improvements are the highest cost per square foot, significantly higher than the attic and wall improvements. Estimated costs included a reasonable sum to excavate the perimeter of the foundation to install slab and foundation insulation below grade.

Future expansion plans may result in the complete removal of the Eastern section of the building. This may discourage investment into improvements for that section. It is estimated that the recommended attic and wall improvements for that section would pay for itself in approximately one heating season. Unless the expansion plans are implemented within the next 18 months, the investment into the thermal boundary and air barrier improvements for the Eastern section would be a cash positive transaction.

OVERVIEW

For each section of the report thermal images from the inspected building were used unless annotated as “file images.” The “comments” for each section specifically pertain to the inspected building and are used for additional clarification or explanations.

Assessed R values are for “whole wall R values” which is a total R value for the assembly as a whole. This takes into account the type, amount, and quality of the existing insulation, incorporates the thermal resistance of the existing framing and incorporates the percentage of total framing area compared to insulated cavity area. R values recommended for improvements are considered minimum R values that are currently cost effective with consideration to current fuel prices and the type of insulation contemplated. Greater R values will reduce energy losses further but at diminishing returns on investment. Installing greater R values than recommended is encouraged particularly if you believe energy prices will significantly rise in the future.



The data collected from testing, deficiencies found during inspection, and recommendations are organized, cataloged and presented in seven separate sections at the beginning of this report. These sections include:

- Observations and Test Data Section
- Estimated Energy Savings & Environmental Impact
- Air Infiltration Report – Total Air Leakage Calculated
- Thermal Boundary Report
- Air Barrier Report
- Other Improvements and Considerations Section
- Health Safety & Building Durability Section

It is important to note that a quality contractor may have different methods or ideas to remediate the problems noted in this report and may make additional recommendations to achieve the same objective towards air sealing and improving the thermal boundary. Contractors that have achieved the Building Performance Institute’s (BPI) certification in their field have demonstrated advanced proficiency and are highly qualified.

A gravity draft boiler and furnace is located in the building. You should be aware that air sealing could impact the pressures in this zone which could affect the draft of combustion appliances, such as your boiler, particularly when dryers, fans or other draft appliances are running. Please refer to the warning concerning this possibility at the bottom of the air infiltration report.

Building Diagrams



Building Pictures



OBSERVATIONS & TEST DATA

Building Envelope Air Leakage Testing

Air leakage testing was accomplished utilizing a calibrated blower door to determine the structure's overall air leakage rate. This test requires a 50 Pascal (Pa) pressure differential with reference to outside and adjusted for the normal baseline pressure of the structure. Test data, and the data normalized to various denominations are provided below.

Section	Sq. Feet	Volume	CFM 50	CFM / ft2	ACH 50	ACHn	Leakage Area Sq. Inches	Leakage Area Sq. Ft
Entire Structure	6032	74196	10980	1.82	6.76	0.68	1465	10.17

CFM50: The amount of air flow in cubic feet per minute (CFM) required to maintain a structure at -50 Pascals pressure, with reference to outside and adjusted for structure's normal base line pressure.

ACH50: Number of air exchanges per hour at 50 Pascal pressure differential.

ACHn: Air Changes per Hour. The annual average rate of exchange of conditioned inside air with outside air on an hourly basis at normal pressure, considering structure elevation and exposure. Determined by calculations utilizing structure volume and calibrated blower door measurements.


Leakage Area: An equivalent sharp edge single hole area that would leak at the same flow rate when the hole is subject to the same target test pressures.

Heating Fuel Consumption Analysis

An analysis was conducted using the fuel consumption for the 2010 heating season with a reported consumption of 2152 gallons. Occupants reported the use of electric space heaters during winter months to supplement zonal heating. Gallons consumed were adjusted by 10 % to account for and convert the supplemental electric heating fuel.


BTUs Per Sq-Ft of Conditioned Space					
Gallons of Fuel Consumed	Converted to Millions of BTUs	Sq-FT of Heated Space	BTUs per Sq-ft	Average For Climate Zone	Difference From Average
2367	331.8 MBtus	6032	55,006	38,860*	+ 41.5%
Note: Data from U.S. Energy Information Administration for Non-Mall Commercial Buildings for Climate Zone with greater than 7000 Heating Degree Days					

Estimated Heating Consumption by Building Component



In MMBtu/yr

Annual Energy Costs



Building Shell Measurements and Ratios

Total Area (sq ft)	
Conditioned Space:	6032
Shell Area:	12002
Foundation Wall:	492.5
Slab Floor:	2670
Frame Floor:	0
Rim And Band Joist:	238.0
Above-Grade Wall:	5566.5
Window:	541.0
Door:	93.7
Ceiling:	3035
Skylight:	0.0
Duct:	0.0

Ratios	
Window-to-Wall:	0.089
Window-to-Floor:	0.090

Window Area By Orientation (sq ft)	
North:	173.2
Northeast:	0.0
East:	34.9
Southeast:	0.0
South:	233.4
Southwest:	0.0
West:	99.5
Northwest:	0.0

ESTIMATED SAVINGS & ENVIRONMENTAL IMPACT

Annual Building Energy Consumption									
All Fuel Sources Combined and Converted to BTUs									
	Total Annual MBtus Consumed	Total Annual Energy Costs	CO2 (Tons)						
Baseline Building – “As Is”	432.8	\$11,847.00	39.2						
Improvement Packages with Associated Savings									
	Estimated Annual MBtus	Estimated Annual Energy Costs	CO2 Emissions			Energy Savings		Financial Savings	
			CO2 (Tons)	Tons Saved	% From Baseline	MBtus Saved	% From Baseline	Dollars Saved	% From Baseline
Envelope Improvements	265.7	\$7,474.00	24.9	14.3	36%	167.1	39%	\$4,373.00	36%
Envelope & Systems*	246.8	\$7,142.00	23.8	15.4	39%	186	43%	\$4,705.00	39%
Comments: The System modeled was an 87% AFUE replacement oil boiler. Air conditioning systems remain unchanged and geothermal was <i>not</i> modeled. This chart is for total fuel consumption to include air conditioning, lighting and plug loads. A lighting audit was not conducted. Default values for lighting were used based on lumens per square foot. Actual electric energy bills were not available at time of report. Electric load are default loads based upon building size and use.									

Heating Fuel Consumption					
	Total Seasonal Gallons Consumed	Total Seasonal Heating Fuel Costs			
Baseline Building - As Is	2391	\$8,113.00			
Improvement Packages with Associated Savings					
	Estimated Seasonal Gallons	Estimated Seasonal Energy Costs	Savings		
			Gallons Saved	Dollars Saved	% From Baseline
Envelope Improvements	1105	\$3,748.00	1286	\$4,365.00	53%
Envelope & Systems*	1003	\$3,404.00	1388	\$4,709.00	58%
Comments: The System modeled was an 86.5% AFUE replacement oil boiler. Geothermal was not modeled.					


Improvements Modeled to Calculate Estimated Energy Savings

Envelope Improvements	
Air Infiltration	40% Reduction
Uninsulated Framed Walls	Insulate with Dense Packed Cellulose – 4" Cavity Depth
Uninsulated Foundation / Masonry Walls	Add R10 EIFS to 2' below grade
Uninsulated Slab	Add R10 Perimeter Insulation*
Uninsulated Attic	Improve Air Barrier - Insulate to R50
Insulated Attics	Improve Air Barrier – Add Insulation to Achieve R50
Uninsulated Slopes	Dense Pack with Cellulose – 7" Cavity Depth
Attic Side Walls	Insulate with Dense Packed Cellulose – Add R10 Rigid Insulation
Attic Hatches (2)	Weather-strip and insulate to R40
Note: Slab perimeter insulation was included in foundation wall improvements	
Envelope & System Improvements	
Includes All Building Shell Improvements plus new 86.5 % AFUE Oil Fired Boiler	

Comparison of Improved building to Current Building Condition

	Rye Town Hall	IMPROVED	DIFF	% DIFF
HEATING SEASON (MMBtu/yr)				
Ceilings/Roofs	34.7	11.2	23.5	67.7%
Rim/Band Joists	6.2	6.2	0.0	0.6%
Above Grade Walls	120.3	54.8	65.5	54.5%
Foundation Walls	30.3	6.0	24.2	80.1%
Doors	5.9	5.2	0.7	12.0%
Windows/Skylights	37.8	39.6	-1.8	-4.7%
Frame Floors	0.0	0.0		
Crawl Space/Unht Bsmt	0.0	0.0		
Slab Floors	23.4	12.5	10.9	46.6%
Infiltration	148.4	88.5	59.9	40.4%
Mechanical Ventilation	0.0	0.0		
Ducts	0.0	0.0		
Active Solar	0.0	0.0		
Sunspace	0.0	0.0		
Internal Gains	-75.2	-70.6	-4.6	-6.1%
Total	331.8	153.3	178.4	53.8%

In MBtu/yr



AIR INFILTRATION REPORT



An air infiltration Report created from TECTITE Software is provided separately

Calibrated Blower Door Measurement: 1098 CFM @ -50 Pascals reference to outside adjusted for building baseline pressure

Zone: 2
Exposure: Normal
Heating Degree Days: Software determined for location
Mechanical Ventilation: No
Software Modeling Performed: Yes

Air Infiltration of Building Tested: 0.68ACHn
6.76 ACH @ 50 Pa

Estimated Cost of Excess Air Leakage: \$1,621.00 per heating season

Savings @ \$ 3.40 / Gallon

* Based on boiler efficiency of 78 %






Definitions:

ACHn – Air Changes per Hour. The average annual rate of exchange of conditioned inside air with outside air on an hourly basis at normal house pressure, considering house elevation and exposure. Determined by calculations utilizing house volume and calibrated blower door measurements.

Warning: Many Combustion Appliances such as furnaces, boilers, water heaters etc. obtain air for combustion and draft from inside the building envelope. Such appliances require a specific amount of air volume and/or flow to function properly and the required volume and/or flow is cumulative for multiple appliances. The MVG addressed in your report is for indoor air quality only and does not take into consideration the required air volume and/or flow of your combustion appliances which utilize indoor air for their operation. Diligence should be observed to ensure that air sealing the building envelope does not adversely impact the proper functioning and drafting of your combustion appliances. If there is any doubt whether your combustion equipment utilizes indoor air for combustion and drafting, or if future air sealing efforts may degrade their function, an appropriate HVAC contractor, and/or local building inspector familiar with your equipment can and should be consulted. Failure to provide the appropriate amount of combustion air volume and/or air flow can result in back drafting, carbon monoxide spillage into your building, and flame “roll out” of its combustion chamber.


THERMAL BOUNDARY REPORT

Main Attic Spaces

Assessment								Recommendations			
Location: Section "A"								<input type="checkbox"/> Relocate Thermal Boundary to Slopes and Gable Walls <input checked="" type="checkbox"/> Keep Thermal Boundary at Present Location <input type="checkbox"/> No Improvements Recommended			
Thermal Boundary Location: <input checked="" type="checkbox"/> Floor <input type="checkbox"/> Slope & Gables <input type="checkbox"/> None											
Assembly	Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Improve	Install Insulation - Type	Depth	Install Air Barrier / Rigid Insulation - Type
Floor	2x7-26	58 x 38	2204	Fiberglass	12"	2	38	<input checked="" type="checkbox"/> Floor:	1" Closed Cell & 4" Cellulose	5"	
Slope		x	0					<input type="checkbox"/> Slope:			
Gable Wall		x	0					<input type="checkbox"/> Gable Wall			
Side Wall		x	0					<input type="checkbox"/> Side Wall			
Attic Flooring <input checked="" type="checkbox"/> Open Joist <input type="checkbox"/> Planked Floor <input type="checkbox"/> Plywood Covered Attic Access <input type="checkbox"/> Pull Down Stairs <input checked="" type="checkbox"/> Hatch <input type="checkbox"/> Stairs <input type="checkbox"/> None Access Dimensions: 36 x 24 Inches								<input type="checkbox"/> Seal Gap Between Chimney & Framing (Comply with Code) <input type="checkbox"/> Install Insulation Dam Around Chimney (Comply with Code) <input type="checkbox"/> Install Recessed Light Domes (Comply with Code) Qty: <input type="checkbox"/> Seal Plumbing Penetrations and / or Chase <input checked="" type="checkbox"/> Seal Electrical Penetrations through Framing <input checked="" type="checkbox"/> Seal Wall Top Plates Prior to Insulating floor <input type="checkbox"/> Seal Gap Around HVAC Penetrations <input checked="" type="checkbox"/> Install Insulation Dam Around Attic Hatch (Comply with Code) <input checked="" type="checkbox"/> Insulate and Weather-strip Hatch (See Hatch Section) <input type="checkbox"/> Add Propa Vents or Baffles at Exterior walls – Qt: <input type="checkbox"/> Install Insulation Dam Around Gable Vents <input type="checkbox"/> Protect Floor Insulation from Soffit Air Flow with Blocking <input type="checkbox"/> Seal Drop Soffits with Air Barrier Sealed to Sheetrock <input type="checkbox"/> Access Cut is Required to Gain Entry <input type="checkbox"/>			
<input type="checkbox"/> Assembly is Not Insulated <input checked="" type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Bath Fans Exhaust to this Space <input type="checkbox"/> Bath Fan & Ductwork Present <input type="checkbox"/> HVAC Ducts / Air Handlers are Present <input type="checkbox"/> Drop Soffits are Present <input type="checkbox"/> Recessed Lights Present – Qty: <input type="checkbox"/> Chimneys are Present – Qty: <input type="checkbox"/> Water Pipes are Present Unsafe Wiring was Noticed <input type="checkbox"/> Sky Light Shafts are Present - Signs of Water Leaks Present <input type="checkbox"/> Side Wall Insulation not in Full Contact w/ Air Barrier (Batts not Split Around Wiring) <input type="checkbox"/> Side Wall / Gable Wall Insulation is Not Protected with an Air Barrier <input type="checkbox"/> Floor Insulation is Exposed to Soffit Air Flow <input type="checkbox"/> Floor Insulation is not in Full Contact with Air Barrier (Batts with Strapping) <input checked="" type="checkbox"/> Excessive Air Leakage Through Primary Air Barrier <input type="checkbox"/>								<input checked="" type="checkbox"/> Insulation Must be Moved to Conduct Improvements <input checked="" type="checkbox"/> Existing Insulation can be Re-used <input type="checkbox"/> Floor Planking requires Removal Prior to Insulating <input type="checkbox"/> Install Cross Framing to Add Cavity Depth (Comply with Code) <input type="checkbox"/> Replace Bath Fan Prior to Installing Insulation <input type="checkbox"/> Replace Bath Vent Line: <input type="checkbox"/> Insul Flex <input type="checkbox"/> Insul Hard <input type="checkbox"/> Install Vent Exhaust Hood: <input type="checkbox"/> Soffit <input type="checkbox"/> Wall <input type="checkbox"/> Seal Air Ducts <input type="checkbox"/> Add Duct Insulation <input type="checkbox"/> Install Gable Vents – Qty: <input checked="" type="checkbox"/> Install "Catwalk" Above Planned Insulation Level <input type="checkbox"/> Insulate Water Pipes / Burry Under Insulation Correct Unsafe Wiring Prior to Insulating Fix Water Leaks Prior to Insulating <input type="checkbox"/> <input type="checkbox"/>			
								<p>Comments: This attic section is insulated with approximately 12" of blown fiberglass insulation. The ceiling assembly for this section is comprised of a metal ceiling installed over a plaster and lathe ceiling. Currently the old plaster is the primary air barrier and is failing with many gaps and defects observed. It is recommended that the blown fiberglass be removed and a 1" flash spray installed directly over the lathe to create a new air barrier. Once this is accomplished the original blown fiberglass can be re-used and capped with an additional 4" of cellulose insulation to bring the total R value of the assembly to R50+. The perimeter of this attic section slopes down to the walls. An insulation dam would be required approximately 4' inside of the perimeter to allow the flat ceiling area to maintain a full 16" insulation depth. Additional insulation would be required for the sloped sections to ensure the entire sloped section maintains adequate insulation depth. It is also highly recommended that a "catwalk" be built approximately 17" above the level of the lathe and plaster to allow adequate access from the existing hatch to the opposite end of the attic without having to walk through the new insulation. The attic hatch is not insulated. It is recommended that this hatch be rebuilt to include a full height insulation dam, weather-stripped and insulated to R40.</p>			
											
											
Hatch								Lathe & Plaster Ceiling			
								Metal Ceiling Under			
								Insulation Dam Required			

Main Attic Spaces

Assessment								Recommendations			
Location: Section "B"								<input type="checkbox"/> Relocate Thermal Boundary to Slopes and Gable Walls <input checked="" type="checkbox"/> Keep Thermal Boundary at Present Location			
Thermal Boundary Location: <input checked="" type="checkbox"/> Floor <input type="checkbox"/> Slope & Gables <input type="checkbox"/> None								<input type="checkbox"/> No Improvements Recommended			
Assembly	Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Improve	Install Insulation - Type	Depth	Install Air Barrier / Rigid Insulation - Type
Floor	2x7-26	36 x 15	540	Fiberglass	12"	2	38	<input checked="" type="checkbox"/> Floor:	1" Closed Cell & 4" Cellulose	5"	
Slope		x	0					<input type="checkbox"/> Slope:			
Gable Wall		x	0					<input type="checkbox"/> Gable Wall			
Side Wall	3x4-32	36 x 5.9	212	None			4.2	<input checked="" type="checkbox"/> Side Wall	Blown Cellulose	4"	2" Extruded Polystyrene
Light Shaft		x	0					<input type="checkbox"/> Light Shaft			
Attic Flooring <input checked="" type="checkbox"/> Open Joist <input type="checkbox"/> Planked Floor <input type="checkbox"/> Plywood Covered								<input checked="" type="checkbox"/> Seal Gap Between Chimney & Framing (Comply with Code)			
Attic Access <input type="checkbox"/> Pull Down Stairs <input checked="" type="checkbox"/> Hatch <input type="checkbox"/> Stairs <input type="checkbox"/> None								<input checked="" type="checkbox"/> Install Insulation Dam Around Chimney (Comply with Code)			
Access Dimensions: x Inches								<input type="checkbox"/> Install Recessed Light Domes (Comply with Code) Qty:			
<input type="checkbox"/> Assembly is Not Insulated <input checked="" type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Bath Fans Exhaust to this Space <input type="checkbox"/> Bath Fan & Ductwork Present <input type="checkbox"/> HVAC Ducts / Air Handlers are Present <input type="checkbox"/> Drop Soffits are Present <input type="checkbox"/> Recessed Lights Present – Qty: <input checked="" type="checkbox"/> Chimneys are Present – Qty: :1 <input type="checkbox"/> Water Pipes are Present <input type="checkbox"/> Unsafe Wiring was Noticed <input type="checkbox"/> Sky Light Shafts are Present – Qty: <input type="checkbox"/> Signs of Water Leaks Present								<input type="checkbox"/> Seal Plumbing Penetrations and / or Chase <input checked="" type="checkbox"/> Seal Electrical Penetrations through Framing <input checked="" type="checkbox"/> Seal Wall Top Plates Prior to Insulating floor <input type="checkbox"/> Seal Gap Around HVAC Penetrations <input type="checkbox"/> Install Insulation Dam Around Attic Hatch (Comply with Code) <input type="checkbox"/> Insulate and Weather-strip Hatch (See Hatch Section) <input type="checkbox"/> Add Propa Vents or Baffles at Exterior walls – Qt: <input type="checkbox"/> Install Insulation Dam Around Gable Vents <input type="checkbox"/> Protect Floor Insulation from Soffit Air Flow with Blocking <input type="checkbox"/> Seal Drop Soffits with Air Barrier Sealed to Sheetrock <input type="checkbox"/> Access Cut is Required to Gain Entry			
<input type="checkbox"/> Side Wall Insulation not in Full Contact w/ Air Barrier (Batts not Split Around Wiring) <input type="checkbox"/> Side Wall / Gable Wall Insulation is Not Protected with an Air Barrier <input type="checkbox"/> Floor Insulation is Exposed to Soffit Air Flow <input type="checkbox"/> Floor Insulation is not in Full Contact with Air Barrier (Batts with Strapping) <input type="checkbox"/> Space Could Not be Inspected – Best Estimate <input checked="" type="checkbox"/> Excessive Air Leakage Through Primary Air Barrier								<input checked="" type="checkbox"/> Insulation Must be Moved to Conduct Improvements <input checked="" type="checkbox"/> Existing Insulation can be Re-used <input type="checkbox"/> Floor Planking requires Removal Prior to Insulating <input type="checkbox"/> Install Cross Framing to Add Cavity Depth (Comply with Code) <input type="checkbox"/> Replace Bath Fan Prior to Installing Insulation <input type="checkbox"/> Replace Bath Vent Line: <input type="checkbox"/> Insul Flex <input type="checkbox"/> Insul Hard <input type="checkbox"/> Install Vent Exhaust Hood: <input type="checkbox"/> Soffit <input type="checkbox"/> Wall <input type="checkbox"/> Seal Air Ducts <input type="checkbox"/> Add Duct Insulation <input type="checkbox"/> Install Gable Vents – Qty: <input checked="" type="checkbox"/> Install "Catwalk" Above Planned Insulation Level <input type="checkbox"/> Insulate Water Pipes / Burry Under Insulation <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/> Fix Water Leaks Prior to Insulating			



Comments: This attic section is insulated with 12" of blown fiberglass. However the primary air barrier is the tongue and groove wood ceiling. It was assessed via blower door testing that there is excessive air exfiltration through the tongue and groove ceiling assembly and through the fiberglass insulation. The same recommendations are made as was made for Section "A", remove the blown fiberglass to one side of the attic and overspray the attic side of the tongue and groove ceiling with a 1" flash spray of closed cell spray foam to create an adequate air barrier. Once this is accomplished the fiberglass insulation can be re-installed and capped with 4" of cellulose insulation to bring the entire assembly to R50. There is a chimney located in the Northwest corner. Any gap between the chimney and the framing should be sealed with code approved methods and an insulation dam built around the chimney to maintain code required free air space requirements around the chimney. The West wall of this attic is a wall to conditioned space. This wall is not insulated. It is recommended that cellulose insulation be dense packed into this wall assembly from that attic side. It may be possible to insulate this wall assembly from the associated open top plates. 2" XPS rigid insulation can then be installed over the assembly to add R10 continuous insulation. All seams of the rigid insulation should be taped and the perimeter sealed. An alternative to using 2" XPS rigid insulation would be to use 2" of closed cell insulation applied directly to the attic side wall after it is dense packed with cellulose.




Main Attic Spaces


Assessment								Recommendations			
Location: Section "C"								<input type="checkbox"/> Relocate Thermal Boundary to Slopes and Gable Walls <input checked="" type="checkbox"/> Keep Thermal Boundary at Present Location			
Thermal Boundary Location: <input type="checkbox"/> Floor <input type="checkbox"/> Slope & Gables <input checked="" type="checkbox"/> None								<input type="checkbox"/> No Improvements Recommended			
Assembly	Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Improve	Install Insulation - Type	Depth	Install Air Barrier / Rigid Insulation - Type
Floor	2x3-53	6.9 x 31.5	217	None				<input checked="" type="checkbox"/> Floor:	1" Closed Cell & 4" Cellulose	16"	
Slope	2x6-21	1.5 x 49	73	None				<input checked="" type="checkbox"/> Slope:	Blown Cellulose	4"	
Gable Wall		x	0					<input type="checkbox"/> Gable Wall			
Side Wall	3x4-32	34 x 4	136	None				<input checked="" type="checkbox"/> Side Wall	Blown Cellulose	4"	2" Extruded Polystyrene
Attic Flooring <input checked="" type="checkbox"/> Open Joist <input type="checkbox"/> Planked Floor <input type="checkbox"/> Plywood Covered								<input type="checkbox"/> Seal Gap Between Chimney & Framing (Comply with Code)			
Attic Access <input type="checkbox"/> Pull Down Stairs <input checked="" type="checkbox"/> Hatch <input type="checkbox"/> Stairs <input type="checkbox"/> None								<input type="checkbox"/> Install Insulation Dam Around Chimney (Comply with Code)			
Access Dimensions: 16" x 16" Inches								<input type="checkbox"/> Install Recessed Light Domes (Comply with Code) Qty:			
<input checked="" type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Assembly is Under Insulated								<input type="checkbox"/> Seal Plumbing Penetrations and / or Chase			
<input type="checkbox"/> Bath Fans Exhaust to this Space <input type="checkbox"/> Bath Fan & Ductwork Present								<input type="checkbox"/> Seal Electrical Penetrations through Framing			
<input type="checkbox"/> HVAC Ducts / Air Handlers are Present <input type="checkbox"/> Drop Soffits are Present								<input type="checkbox"/> Seal Wall Top Plates Prior to Insulating floor			
<input type="checkbox"/> Recessed Lights Present – Qty: <input type="checkbox"/> Chimneys are Present – Qty: :								<input type="checkbox"/> Seal Gap Around HVAC Penetrations			
<input type="checkbox"/> Water Pipes are Present <input type="checkbox"/> Unsafe Wiring was Noticed								<input checked="" type="checkbox"/> Install Insulation Dam Around Attic Hatch (Comply with Code)			
<input type="checkbox"/> Sky Light Shafts are Present – Qty: <input checked="" type="checkbox"/> Signs of Water Leaks Present								<input checked="" type="checkbox"/> Insulate and Weather-strip Hatch (See Hatch Section)			
<input type="checkbox"/> Side Wall Insulation not in Full Contact w/ Air Barrier (Batts not Split Around Wiring)								<input type="checkbox"/> Add Propa Vents or Baffles at Exterior walls – Qt:			
<input checked="" type="checkbox"/> Side Wall / Gable Wall Insulation is Not Protected with an Air Barrier								<input type="checkbox"/> Install Insulation Dam Around Gable Vents			
<input checked="" type="checkbox"/> Excessive Air Leakage Through Primary Air Barrier								<input type="checkbox"/> Protect Floor Insulation from Soffit Air Flow with Blocking			
<input type="checkbox"/> Floor Insulation is not in Full Contact with Air Barrier (Batts with Strapping)								<input type="checkbox"/> Seal Drop Soffits with Air Barrier Sealed to Sheetrock			
								<input type="checkbox"/> Remove and Discard Old Insulation Prior to Insulating			
								<input type="checkbox"/> Remove / Discard FG Batts within 4' of perimeter			
								<input type="checkbox"/> Floor Planking requires Removal Prior to Insulating			
								<input checked="" type="checkbox"/> Install Cross Framing to Add Cavity Depth (Comply with Code)			
								<input type="checkbox"/> Replace Bath Fan Prior to Installing Insulation			
								<input type="checkbox"/> Replace Bath Vent Line: <input type="checkbox"/> Insul Flex <input type="checkbox"/> Insul Hard			
								<input type="checkbox"/> Install Vent Exhaust Hood: <input type="checkbox"/> Soffit <input type="checkbox"/> Wall			
								<input type="checkbox"/> Seal Air Ducts <input type="checkbox"/> Add Duct Insulation			
								<input type="checkbox"/> Install Gable Vents – Qty:			
								<input checked="" type="checkbox"/> Install "Catwalk" Above Planned Insulation Level			
								<input type="checkbox"/> Insulate Water Pipes / Burry Under Insulation			
								<input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating			
								<input checked="" type="checkbox"/> Fix Water Leaks Prior to Insulating			


Comments: This attic space was found uninsulated. Occupants report water leaks from this attic section. Interview with workers that utilize this space stated that most of the water leaks seemed to occur during the winter months. It is possible that these leaks are actually the result of condensation from warm interior air condensing in the cold space; however the workers also reported leaks during the recent hurricane. Before any improvements are completed in this space the roof shingles and associated flashing should be inspected by a qualified roofer with appropriate repairs made as necessary. This ceiling assembly is uninsulated tongue and groove wood with short uninsulated slopes around the exterior perimeter. There is an attic side wall on the West side that separates this attic space from the conditioned space of Section "B". Inspection revealed this side attic wall to be mostly uninsulated. Rosin paper installed on this side attic wall was used as the original air barrier. This paper has failed and provides little air barrier value. Both this ceiling and the side attic wall contribute significantly to the overall air leakage of this building in that neither has an appropriate air barrier. The framing of the flat ceiling area is assessed as inadequate to support a worker. This can be corrected by the installation of 2x6 framing between the ceiling rafters and the side wall to create solid support for work to be accomplished. This framing should be installed 15" above the ceiling level so future access can be gained after the insulation is installed. As with the recommendations for the previous attic spaces, it is recommended that an adequate air barrier be established by installing 1" closed cell insulation on the attic side of the flat ceiling area. This would then be capped with 14" of blown cellulose to bring the ceiling to R50. The side attic wall would require a dense packed cellulose blow. Once the cavities are fully insulated than 2" XPS rigid insulation should be installed over the side wall to create an adequate air barrier and to provide a layer of

continuous R10 insulation. All seams should be taped and the perimeter sealed. A 2" application of closed cell insulation could be substituted for the XPS rigid insulation. The small sloped assembly surrounding the exterior perimeter of this space would require a dense packed cellulose blow. Due to the limited cavity depth of these slopes the maximum R-value achievable by dense packing alone would be R20. Consideration should be given to installing 2" polyisocyanurate on the interior sides of the sloped assemblies to be covered by sheetrock. This combination of dense packing the slopes and the additional R13 provided by the continuous insulation would provide R33. The hatch assembly would require full R40 Insulation, weather-stripping and an insulation dam.



Attic Hatches

Assembly	Assessment	Recommendations
Attic Hatch Space 1	Location: Section "A"	<input checked="" type="checkbox"/> Add Insulation to Achieve R40 – Amount: 8" Insulation Type: 2" Extruded Polystyrene
	Hatch Material: <input type="checkbox"/> Sheetrock <input type="checkbox"/> Plywood <input checked="" type="checkbox"/> Wood Plank	<input checked="" type="checkbox"/> Replace Hatch with Plywood Hatch <input checked="" type="checkbox"/> Install Weather Stripping
	Type: <input checked="" type="checkbox"/> Hatch <input type="checkbox"/> Pull Down Stairs	<input checked="" type="checkbox"/> Install Insulation Dam <input checked="" type="checkbox"/> Build / Install "Thermadome"
	Insulation Type: Uninsulated Insulation Depth:	<input type="checkbox"/> Larger Hatch is Required for Worker Access
	Insulation Grade: Assessed R-Value:	<input type="checkbox"/>
	Hatch Dimensions: 36"x24"	<input type="checkbox"/>
 <p>Comments: It is recommended that this hatch be reconstructed to provide a fully weather-stripped removable hatch insulated to a minimum of R40.</p>		


Assembly	Assessment	Recommendations
Attic Hatch Space 2	Location: Section "C"	<input checked="" type="checkbox"/> Add Insulation to Achieve R40 – Amount: 8" Insulation Type: 2" Extruded Polystyrene
	Hatch Material: <input type="checkbox"/> Sheetrock <input type="checkbox"/> Plywood <input checked="" type="checkbox"/> Wood Plank	<input type="checkbox"/> Replace Hatch with Plywood Hatch <input checked="" type="checkbox"/> Install Weather Stripping
	Type: <input checked="" type="checkbox"/> Hatch <input type="checkbox"/> Pull Down Stairs	<input type="checkbox"/> Build / Install "Thermadome"
	Insulation Type: Uninsulated Insulation Depth:	<input checked="" type="checkbox"/> Larger Hatch is Required for Worker Access
	Insulation Grade: Assessed R-Value:	<input type="checkbox"/>
	Hatch Dimensions: 16"x16"	<input type="checkbox"/>
 <p>Comments: It is recommended that this hatch be reconstructed to provide a fully weather-stripped removable hatch insulated to a minimum of R40. This hatch may require enlargement to provide adequate worker access.</p>		

Exterior Walls

Assessment							Recommendations		
Location: Framed Walls – Sections “A” & B” - 1st Floor Only							<input checked="" type="checkbox"/> Recommend Improvements – For Areas Described in Comments <input type="checkbox"/> No Improvements Recommended		
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
3x4-32	170 X 8.25	1402	Blown Fiberglass	4"	2	12.7			
Interior Surface: Sheetrock			Exterior Cladding: Wood Clap						
<input type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Insulation is Not Protected from Air <input type="checkbox"/> Excess Air Exchange w/ Exterior <input type="checkbox"/> Wall is “Balloon” Framed <input type="checkbox"/>			<input type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Chimneys are Present – <input type="checkbox"/> Signs of Water Leaks Present <input type="checkbox"/> Unsafe Wiring is Present				<input type="checkbox"/> Exterior Paint Should be Checked for Lead <input type="checkbox"/> Air Seal Interior Penetrations <input type="checkbox"/> Requires an Exterior Insulation Blow <input type="checkbox"/> Batts can be Installed from Interior <input type="checkbox"/> Air Seal Exterior Penetrations		
							<input type="checkbox"/> Add Exterior Insulation when Exterior Siding is Replaced <input type="checkbox"/> Requires an Interior Insulation Blow <input type="checkbox"/> Comply with Lead Paint Abatement Procedures <input type="checkbox"/> Fix Water Leaks Prior to Insulating <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/>		
Associated Rim Band Between Conditioned Floor Levels (Not Basement or Crawlspace Rim Bands)							Associated Rim Band Between Conditioned Floor Levels		
Framing	Linear Ft	Insulation	Depth	Grade	R-Value		Install Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
6x6	238	None			7				
<input type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Excess Air Exchange w/ Exterior <input type="checkbox"/> Wall is “Balloon” Framed <input type="checkbox"/> Not able to Assess <input type="checkbox"/>			<input type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Signs of Water Leaks Present <input type="checkbox"/> Unsafe Wiring is Present <input type="checkbox"/> Wood Rot is Present <input type="checkbox"/>				<input type="checkbox"/> Air Seal Penetrations <input type="checkbox"/> Air Seal Gaps <input type="checkbox"/> Requires an Exterior Insulation Blow <input type="checkbox"/> Ensure Rigid Insulation is Sealed in Place <input type="checkbox"/> Remove and Discard Existing Insulation		
							<input type="checkbox"/> Ensure Rim Insulation Ties into Foundation Insulation <input type="checkbox"/> Fix Water Leaks Prior to Insulating <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/> Correct Wood Rot Prior to Insulating <input type="checkbox"/>		
<p>Comments: The walls for sections “A” and “B” are comprised of an elevated foundation wall with a framed wall above. The framed section of these walls has been retrofitted with blown fiberglass insulation. A defect was found with the wall bays associated with the stair well on the North side. The interior wall section below the stairwell did not have interior sheathing and the insulation fell out of these bays after installation. Access to the underside of the stairs is by an opening from the boiler room. It is recommended that OSB sheathing be installed on the interior wall side and the specific bays dense packed with cellulose insulation. No notable defects were found with the remaining framed walls for sections “A” and “B”. However the lower half of these walls has an elevated foundation that is framed on the interior. Some sections of Section “B” have full height brick walls. It was assessed through infrared imaging that the interior framed portions of these masonry walls are not insulated. The “Foundation Wall” section of this report will describe the recommended remedial measures for those specific assemblies.</p>									

Exterior Walls


Assessment							Recommendations		
Location: Section "C" – 1st Floor only							<input checked="" type="checkbox"/> Recommend Improvements	<input type="checkbox"/> No Improvements Recommended	
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
2X4-16	36 x 6.5	234	Fiberglass	4"	2	1.6 - 10.2			
Interior Surface: Sheetrock <input checked="" type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Insulation is Not Protected from Air <input type="checkbox"/> Excess Air Exchange w/ Exterior <input type="checkbox"/> Wall is "Balloon" Framed <input type="checkbox"/>							Exterior Cladding: Wood Clap <input checked="" type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Chimneys are Present – <input type="checkbox"/> Signs of Water Leaks Present <input type="checkbox"/> Unsafe Wiring is Present		
							<input type="checkbox"/> Exterior Paint Should be Checked for Lead <input type="checkbox"/> Air Seal Interior Penetrations <input type="checkbox"/> Requires an Exterior Insulation Blow <input type="checkbox"/> Batts can be Installed from Interior <input type="checkbox"/> Air Seal Exterior Penetrations		
							<input checked="" type="checkbox"/> Add Interior Insulation to Uninsulated Masonry Surfaces <input checked="" type="checkbox"/> Comply with Building Code Thermal Barrier Requirements <input type="checkbox"/> Comply with Lead Paint Abatement Procedures <input type="checkbox"/> Fix Water Leaks Prior to Insulating <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/>		




Comments: This section appears to have been an open porch that has been framed in. The framed portions of this section's walls were determined to be insulated via infrared imaging and visual inspection and are assessed at R10.2 for "whole wall" R-value. The Southern closet however has uninsulated masonry walls and a very low R-value and leaky door. The uninsulated brick is assessed an R-value of 1.6 and the door is approximately R1. The East wall of this section has uninsulated brick pillars, and the North wall has uninsulated exposed concrete on the lower half. The foundation wall section of this report provides improvement recommendations that include exterior insulation for the masonry foundations / walls. For this particular section of the building there is an option to put insulation on the interior of the masonry walls instead of the exterior, or both could be accomplished. 2.5" extruded polystyrene protected with a code approved thermal barrier, such as sheetrock, would be appropriate and provide an R13 insulation level. The brick pillars in the East wall and the exposed concrete on the North wall should also be covered with 2.5" rigid foam board with sheetrock. It appears that the exterior door in the South closet is not used and is sealed shut. If this door is not required then it is recommended that this door be fully sealed to create a weather tight barrier then insulated over with rigid insulation and a thermal barrier.



Uninsulated / Leaky Door




Uninsulated Brick Pillars




Uninsulated Concrete

Exterior Walls

Assessment							Recommendations		
Location: Section "A" - 2 nd Floor							<input checked="" type="checkbox"/> Recommend Improvements	<input type="checkbox"/> No Improvements Recommended	
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
3x4-32	17.33 x 156	2309	None			4.2			
Interior Surface: Sheetrock			Exterior Cladding: Wood Clap				<input checked="" type="checkbox"/> Exterior Paint Should be Checked for Lead	<input type="checkbox"/> Add Exterior Insulation when Exterior Siding is Replaced	
<input checked="" type="checkbox"/> Assembly is Not Insulated			<input type="checkbox"/> Assembly is Under Insulated				<input checked="" type="checkbox"/> Air Seal Interior Penetrations	<input type="checkbox"/> Requires an Interior Insulation Blow	
<input type="checkbox"/> Insulation is Not Protected from Air			<input type="checkbox"/> Chimneys are Present –				<input checked="" type="checkbox"/> Requires an Exterior Insulation Blow	<input checked="" type="checkbox"/> Comply with Lead Paint Abatement Procedures	
<input type="checkbox"/> Excess Air Exchange w/ Exterior			<input type="checkbox"/> Signs of Water Leaks Present				<input type="checkbox"/> Batts can be Installed from Interior	<input type="checkbox"/> Fix Water Leaks Prior to Insulating	
<input checked="" type="checkbox"/> Wall has open top plates			<input type="checkbox"/> Unsafe Wiring is Present				<input checked="" type="checkbox"/> Air Seal Exterior Penetrations	<input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating	
<input type="checkbox"/>								<input type="checkbox"/>	



Comments: The Sq-Ft of the wall surface area listed above excludes the surface areas of the windows and is the actual surface area of the wall cavities that require insulation. Infrared imaging and visual inspection from the attic revealed these bays to be void of insulation. Due to the open wall top plates, minor amounts of blown fiberglass have fallen into these bays when the blown fiberglass was installed in the attic. Improvements to these walls will require an exterior cellulose blow. Due to the age of this structure, lead paint abatement procedures would be applicable unless approved RRP testing determines the absence of lead. The interior sheetrock has many unsealed gaps and seams. Interior air sealing should first be accomplished prior to dense packing cellulose to prevent excessive dust and debris from entering the office spaces and to reduce infiltration. Of important note is that there are air ducts in both the North and South Walls. It was not determined during the audit if there is actual ductwork installed in the wall cavity or if the wall cavity itself was panned off and used as the air duct. It is *extremely* important that the follow on insulation contractor first determine if actual air ducts are present in these wall bays prior to blowing insulation into these wall cavities. For either scenario it is highly inefficient to have ductwork inside an exterior wall cavity, and would be significantly worse if the cavity itself was used as the air duct. Even with perfectly tight ductwork (highly doubtful) these specific wall bays can not be properly insulated while the ductwork remains. It is highly recommended that this particular ductwork be re-routed to the interior of the primary air barrier (interior sheetrock).




Infrared Images Showing Uninsulated Walls

Exterior Walls


Assessment							Recommendations		
Location: Section "B" – 2nd Floor							<input checked="" type="checkbox"/> Recommend Improvements	<input type="checkbox"/> No Improvements Recommended	
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
3x4-32	11.5 x 32	340	None			4.9	Dense Packed Cellulose	4"	
Interior Surface: 3/4" Wood Panel Exterior Cladding: Wood Clap <input checked="" type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Assembly is Under Insulated <input checked="" type="checkbox"/> Inadequate Air Barrier <input checked="" type="checkbox"/> Chimneys are Present – 1 <input type="checkbox"/> Excess Air Exchange w/ Exterior <input type="checkbox"/> Signs of Water Leaks Present <input checked="" type="checkbox"/> Wall has open top plates <input type="checkbox"/> Unsafe Wiring is Present <input type="checkbox"/>							<input checked="" type="checkbox"/> Exterior Paint Should be Checked for Lead <input checked="" type="checkbox"/> Air Seal Interior Penetrations <input checked="" type="checkbox"/> Requires an Exterior Insulation Blow <input type="checkbox"/> Batts can be Installed from Interior <input type="checkbox"/> Air Seal Exterior Penetrations	<input type="checkbox"/> Add Exterior Insulation when Exterior Siding is Replaced <input type="checkbox"/> Requires an Interior Insulation Blow <input checked="" type="checkbox"/> Comply with Lead Paint Abatement Procedures <input type="checkbox"/> Fix Water Leaks Prior to Insulating <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/>	

Comments: This section's walls were determined to be uninsulated via infrared inspection. The interior wall surfaces are tongue and groove wood which provides an inadequate air barrier. In addition these walls have many "cut outs" through which wiring had been run. These walls would require and exterior cellulose blow after the holes have been sealed. Lead paint abatement procedures would apply unless the exterior paint tested negative for lead using approved RRP lead testing procedures. The installation of interior 2" extruded polystyrene rigid insulation over the tongue and groove is an additional efficiency upgrade to be considered. This would significantly improve the air barrier reducing infiltration along with providing a layer of continuous R10 insulation. The wall currently is assessed at R5. Dense packing the cavities with cellulose would bring the wall assembly to R14. Dense packing the cavities and adding a layer of R10 interior insulation and sheetrock would bring the assembly to R25 and would provide a superior air barrier. This interior insulation would require a code approved thermal barrier, such as sheetrock. This interior insulation recommendation was not modeled into the energy saving calculations provided previously in this report due to the unlikelihood that this particular improvement would be conducted at this time, but should be considered if funding allows. The square feet provided in the table above are for the opaque wall area exclusive of windows.




Exterior Walls










Assessment							Recommendations		
Location: Section "C" – 2nd Floor							<input checked="" type="checkbox"/> Recommend Improvements	<input type="checkbox"/> No Improvements Recommended	
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Interior Air Barrier / Rigid Insulation - Type
2X4-16	6.5 x 50	292	None			4.9	Dense Packed Cellulose	4"	
Interior Surface: 3/4" Wood Panel <input checked="" type="checkbox"/> Assembly is Not Insulated <input checked="" type="checkbox"/> Inadequate Air Barrier <input type="checkbox"/> Excess Air Exchange w/ Exterior <input checked="" type="checkbox"/> Wall has open top plates <input type="checkbox"/>							Exterior Cladding: Wood Clap <input type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Chimneys are Present – <input type="checkbox"/> Signs of Water Leaks Present <input type="checkbox"/> Unsafe Wiring is Present		
							<input checked="" type="checkbox"/> Exterior Paint Should be Checked for Lead <input checked="" type="checkbox"/> Air Seal Interior Penetrations <input checked="" type="checkbox"/> Requires an Exterior Insulation Blow <input type="checkbox"/> Batts can be Installed from Interior <input type="checkbox"/> Air Seal Exterior Penetrations		
							<input type="checkbox"/> Add Exterior Insulation when Exterior Siding is Replaced <input type="checkbox"/> Requires an Interior Insulation Blow <input checked="" type="checkbox"/> Comply with Lead Paint Abatement Procedures <input type="checkbox"/> Fix Water Leaks Prior to Insulating <input type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input type="checkbox"/>		



Comments: The same recommendations are made for this section as were made for building section "B". These walls were determined to be uninsulated and the tongue and groove provides a poor air barrier. As seen in the associated sections of this report this entire 2nd floor section of this building has uninsulated assemblies to include walls, the sloped ceiling sections and the flat attic section. The door to exterior is a very low R-value door and would be a candidate for replacement. The square feet provided in the table above are for the opaque wall area exclusive of windows and the door.



Foundation Walls

Assessment							Recommendations		
Location: Sections: All – Lower Sections with Masonry or Stone							<input checked="" type="checkbox"/> Recommend Improvements <input type="checkbox"/> No Improvements Recommended		
Framing	Dimensions	Sq-Ft	Insulation	Depth	Grade	R-Value	Install Cavity Insulation - Type	Depth	Install Exterior Rigid Insulation
Masonry	x	674	None			1.5 – 3.0			R 10 EIFS
Interior Surface: Finished <input checked="" type="checkbox"/> Assembly is Not Insulated <input type="checkbox"/> Insulation is Not Protected from Air <input type="checkbox"/> Excess Air Exchange w/ Exterior <input type="checkbox"/> Wall is "Balloon" Framed <input type="checkbox"/>							Exterior Cladding: Exposed Masonry or Stone <input type="checkbox"/> Assembly is Under Insulated <input type="checkbox"/> Chimneys are Present – <input checked="" type="checkbox"/> Signs of Water Leaks Present <input checked="" type="checkbox"/> Unsafe Wiring is Present		
							<input type="checkbox"/> Improve Existing Insulation to Grade 1 <input type="checkbox"/> Remove and Discard Old Insulation <input type="checkbox"/> Cover Exposed Wall Insulation with Air <input type="checkbox"/> Air Seal Penetrations <input type="checkbox"/> Insulate Hatch / Door <input type="checkbox"/> Weather-Strip Hatch / Door		
							<input type="checkbox"/> Ensure Ceiling Insulation is in Full Contact with Subfloor <input type="checkbox"/> Leave Bottom 6" Uninsulated Due to Dampness <input type="checkbox"/> Tape Seams of Rigid Insulation and Seal Perimeter <input checked="" type="checkbox"/> Moisture Problems Must be Corrected Prior to Insulating <input checked="" type="checkbox"/> Correct Unsafe Wiring Prior to Insulating <input checked="" type="checkbox"/> Vent Dryer to Exterior		
							Comments: This building has an uninsulated slab on grade and the lower portions of the foundation walls are uninsulated. Infrared imaging of the foundation wall sections that have finished interiors has lead to the assessment that these foundation walls have no interior insulation. The uninsulated slab on grade along with the uninsulated foundation walls are a significant source of energy losses for this structure. It is recommended that these walls be improved with an Exterior Insulation Finishing System (EIFS) that provides a minimum of R10 with higher R-values preferred. To obtain maximum benefits, and to provide the slab perimeter insulation, it is recommended that the exterior insulation extend 2' below ground level if funding allows. This would require excavation around the perimeter. The below grade exterior rigid should extend down the below grade foundation wall and then horizontal for an additional 2'. If a full 2' depth is not practical due to limitations of funding, then the above grade portion, with as much below grade installation as feasible, is still recommended. One company that specialized in exterior foundation insulation is Associated Concrete Coatings, of Manchester NH. The exterior brick wall segment associated with the "vault" has a through wall vent that presently is covered by the exterior bulletin board on the South Side. Though this vent is covered by the bulletin board, excessive air leakage was noted through this vent. If it is determined that this vent is not required or needed then this vent should be sealed and insulated over.		
									
Section A – South									
Sections B & C – South									
Section C – South									
Section A – North & West									
									
IR Image of Lower Foundation									



Slab Floors

Assembly	Assessment	Recommendations
Slab Floor Space 1	Location: Entire Structure	<input checked="" type="checkbox"/> Add Perimeter Insulation – R-Value: 10 Recommended Type: EIFS Quantity:
	Covering: Combination Floor Dimensions:	<input type="checkbox"/> Recommend Rigid Insulation Installed Between Sleepers when Carpet is Replaced or Space Finished
	LF On Grade: 238 LF Below Grade: 73	<input type="checkbox"/> Cover Exterior Insulation with UV Protection <input type="checkbox"/>
	Insulation Under: No Perimeter Insulation: No	<input type="checkbox"/>
	Insulation Depth: Assessed R-Value: < 1	
	<input type="checkbox"/> Assembly is Under Insulated <input checked="" type="checkbox"/> Assembly Is Not Insulated <input type="checkbox"/> Above Grade Exterior Insulation is not Protected <input type="checkbox"/>	




Comments: The recommendations for the slab perimeter improvements were made in the foundation wall section of this report. An additional improvement to the slabs would be to install R10 rigid insulation on the top side of the slab. Normally this type of installation would install the rigid insulation between pressure treated sleepers mechanically fastened to the slab. A new subfloor would be installed over. Other insulation systems rely upon sleepers installed over a continuous layer of rigid insulation. However this would require a specific compressive strength required of the rigid insulation. This improvement was not modeled into the energy savings calculation provided due to the assessment that it would not be accomplished at this time, and that the best section to conduct this improvement, section "C", may be removed during future expansion.



Windows

Assembly	Assessment	Recommendations
<p>Windows Type 1</p> 	<p>Locations: Throughout Building</p> <p>Assessed U Value: 0.58</p> <p> <input checked="" type="checkbox"/> Single Pane <input type="checkbox"/> Double Pane <input type="checkbox"/> Triple Pane <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl <input type="checkbox"/> < ½ Air Space <input type="checkbox"/> ½ " Air Space <input type="checkbox"/> > ½ " space </p> <p>Low E Coatings: Storm Window: Yes</p> 	<p> <input type="checkbox"/> Add Exterior Storm Window <input type="checkbox"/> Add Interior Storm <input type="checkbox"/> Install Weather-Stripping <input type="checkbox"/> Consider Replacement </p> <p>Comments: Building has significant glazing area. The majority of the windows were single pane wood with storm windows and were assessed as fairly tight. Occupants report that the large 2nd floor windows are very difficult to operate and do not have a counterweight system. New recoil style counter weights systems area available. It is recommended that client consult a contractor that specializes in historic windows to install a counterbalance system to allow windows to be used for ventilation. With these windows operable natural ventilation could be used to a greater extend reducing air conditioning loads.</p>

Exterior Doors


Door Type 1	Assessment	Recommendations	
	Locations: Solid Wood Panel Doors – South and West Entrances Assessed R Value: 1.6	<input type="checkbox"/> Add Exterior Storm Door <input type="checkbox"/> Requires New Weather Stripping <input type="checkbox"/> Requires Door Sweep	
	<input type="checkbox"/> Consider Replacement <input type="checkbox"/> Door Latch Needs Adjusting <input checked="" type="checkbox"/> No Improvements Recommended	Door Glazing Assessment <input checked="" type="checkbox"/> Single Pane <input type="checkbox"/> Double Pane <input type="checkbox"/> Triple Pane <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl <input type="checkbox"/> < ½ Air Space <input type="checkbox"/> ½ " Air Space <input type="checkbox"/> > ½ " space	Comments: Due to the historical nature of the building, replacing the low R-value wood doors for the South and West Entrance is not recommended. However door replacement for the 2 nd Floor East Entrance should be considered.
Door Type 2	Assessment	Recommendations	
	Locations: 1st Floor East Entrance Assessed R Value: 4.4	<input type="checkbox"/> Add Exterior Storm Door <input type="checkbox"/> Requires New Weather Stripping <input type="checkbox"/> Requires Door Sweep	
	<input type="checkbox"/> Consider Replacement <input type="checkbox"/> Door Latch Needs Adjusting <input checked="" type="checkbox"/> No Improvements Recommended	Door Glazing Assessment <input type="checkbox"/> Single Pane <input type="checkbox"/> Double Pane <input type="checkbox"/> Triple Pane <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl <input type="checkbox"/> < ½ Air Space <input type="checkbox"/> ½ " Air Space <input type="checkbox"/> > ½ " space	Comments: This is an insulated door that had minimal air leakage. No recommendation made for this door.
Door Type 3	Assessment	Recommendations	
	Locations: South Side – Section "C" Assessed R Value: 1.2	<input type="checkbox"/> Add Exterior Storm Door <input type="checkbox"/> Requires New Weather Stripping <input type="checkbox"/> Requires Door Sweep	
	<input checked="" type="checkbox"/> Consider Replacement <input type="checkbox"/> Door Latch Needs Adjusting <input type="checkbox"/> No Improvements Recommended	Door Glazing Assessment <input type="checkbox"/> Single Pane <input type="checkbox"/> Double Pane <input type="checkbox"/> Triple Pane <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl <input type="checkbox"/> < ½ Air Space <input type="checkbox"/> ½ " Air Space <input type="checkbox"/> > ½ " space	Comments: It appears that this door is no longer used. It is recommended that this door be sealed and insulated on the interior as recommended previously in this report.

AIR BARRIER / AIR LEAKAGE REPORT

Locations to Consider Air Barrier Improvements						
Assembly		Assessment				Comments
Attic		Major	Moderate	Minor	NA	
Wall Top Plates		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All exterior and interior walls to attics
Electrical Penetrations		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All Penetrating into attics
Plumbing Penetrations		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical / Plumbing / HVAC Chases		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Air Ducts in Wall Cavities, 2 nd Floor North & South
Recessed Lights		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Ceiling Penetrations – Lights or Smoke Alarms		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Attic Hatch		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Both attic hatches were very leaky
HVAC – Gap Between HVAC Boots and Sheetrock		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Chimney – Gap Between Masonry and Chimney		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Unsealed Air Ducts		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Air Ducts in Wall Cavities, 2nd Floor North & South
Office Areas		Major	Moderate	Minor	NA	
Floor to Wall Junctions		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Wall to Ceiling Junctions		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sections B & C
Wall to Wall Junctions		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sections B & C
Gaps or Cracks in Sheetrock or Plaster		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Section A - Holes in Plaster ceiling, gaps in sheetrock on walls
Electrical / Phone / Cable outlets – Walls		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Plumbing Penetrations Through Walls		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Through Tongue & Groove or Wood Planked Walls		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Sections B & C
Windows – Through Window Seals		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windows – Around Trim / Through Rough Opening		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Exterior Doors		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stairs		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Beams		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fireplace – Damper		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fireplace – Gap Between Masonry and Sheetrock or Floor		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fireplace Chimney – Gap Between Chimney and Framing		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Bath Fan – Back Draft Damper		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Consider installing an inline back draft damper in fan vent line
Kitchen Fan – Back Draft Damper		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fan – Vent penetrations		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Dryer Vent Penetration		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Basement or Crawlspace		Major	Moderate	Minor	NA	
Penetrations for Electrical or Plumbing through Floor		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Air Exchange via Cantilevered Floors		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Air Exchange through Framed Floor		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Dryer Vent Penetration		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Penetrations Through Rim Band		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Basement Hatch or Door to Exterior		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Additional Comments:						

SYSTEMS REPORT

Heating System Assessment									
Type of System	<input type="checkbox"/> Forced Hot Air <input checked="" type="checkbox"/> Forced Hot Water <input checked="" type="checkbox"/> Hydro / Air <input type="checkbox"/> Electric Baseboard <input type="checkbox"/> Steam <input type="checkbox"/> Geothermal <input type="checkbox"/> Air Source Heat Pump <input type="checkbox"/> Other								
Fuel Type	Oil	Propane	Kerosene	Electric	Nat. Gas	Cord wood	Wood Pellets	Wood Chips	Other
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Estimated System Efficiency	78% AFUE			Manufacturer			Model Number		
Estimated Age	16-18 Years			Weil-McLain			578		
Programmable Thermostats	Yes								
Note: Refer to "Health & Safety" Section for Results of Combustion Safety Testing Refer to "Other Improvements Recommendations" For Hydronic Pipe Insulation Recommendations									
<input type="checkbox"/> System should be serviced <input type="checkbox"/> Additional Inspection is recommended by a HVAC technician <input checked="" type="checkbox"/> Consider replacement with a high efficiency system <input type="checkbox"/> Replace with high efficiency system at end of current system's useful life <input type="checkbox"/>									
Comments: Detailed inspection of the existing heating systems was not accomplished due to previous contractor evaluating the building's systems and plan to enstall new geothermal system.									



Air Conditioning Assessment

Type of System	<input checked="" type="checkbox"/> Central Air – Air Source <input type="checkbox"/> Central Air – Ground Source <input type="checkbox"/> Window Units <input type="checkbox"/> Floor Units <input checked="" type="checkbox"/> Mini Split <input type="checkbox"/> Multiple Systems are Used <input type="checkbox"/> Other:					
Programmable Thermostats	Yes					
	Age	Efficiency		Size	Manufacturer	Model Number
System 1	16 yrs	10.2 SEER		1.5 Ton	Sanyo	C1822
System 2	16 yrs	10.0 SEER		2 Ton	Sanyo	C2422
System 3	16 yrs	10.0 SEER		2 Ton	Sanyo	C2422
System 4	16 yrs	10.0 SEER		2 Ton	Sanyo	C2422
System 5	16 yrs	10.0 SEER		2 Ton	Sanyo	C2422
System 6	16 yrs	10.0 SEER		5 Ton	American Standard	7A0060A100A
<input type="checkbox"/> System should be serviced <input type="checkbox"/> Additional Inspection is recommended by a HVAC technician <input type="checkbox"/> System is oversized for building <input type="checkbox"/> Consider replacement with a high efficiency system <input type="checkbox"/> Replace with high efficiency system, that is appropriately sized for building, at end of current system's useful life <input checked="" type="checkbox"/> No Improvements Recommended						

Comments: Systems 1-5 are ductless mini-splits. All systems are low efficiency compared to current systems available. Due to plans to have systems replaced with geothermal system, no recommendations are made for the air conditioning systems.



Air Duct Assessment	
---------------------	--

<input type="checkbox"/> No Air Ducts Present	<input checked="" type="checkbox"/> Air Ducts Are Not Sealed	<input type="checkbox"/> Air Ducts Are Under Insulated	
<input type="checkbox"/> Leakage Noted by Feel or IR	<input type="checkbox"/> Air Ducts Tested Leaky	<input checked="" type="checkbox"/> Air Ducts Located in Exterior Wall Cavities	
Tested CFM 25 Leakage of Ducts:	Not Tested	<input type="checkbox"/> Total Leakage Test	<input type="checkbox"/> Leakage to Outside

Recommendations for Air Ducts

<input checked="" type="checkbox"/>	Seal air ducts with mastic	<input type="checkbox"/>	Insulate with R9 minimum	<input type="checkbox"/>	Burry under attic insulation
<input type="checkbox"/>	Seal ducts with closed cell	Recommended Inches of closed cell:			
<input checked="" type="checkbox"/>	Comply with building code and manufacturer's recommendation for application of insulation in proximity of heating system / plenum				
<input type="checkbox"/>					

Comments: The air duct system used for the Hydro air and the 5 ton air conditioning system was not tested. As noted in previous sections of this report additional inspection is recommended to determine if the ducts registers on the upper level of Section "A" North and South Walls have ductwork inside the walls or if the wall cavity was used without dedicated dutwork. It is highly recommended that these wall cavities not be used for duct work and that the ducts be re-routed to remain inside the primary air barrier / thermal boundary. Once this is done then these wall cavities can be completely dense packed with cellulose insulation.

Domestic Hot Water Assessment								
System Type / Information	Tank	Tankless	From Boiler	Insulation Blanket		Heat Traps		Pipe Insulation
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>					
	Electric	Propane	Nat. Gas	Oil	Wood	Solar	Combo	
Fuel Type	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Estimated Efficiency:	70%							
Recommendations For Domestic Hot Water System								
Note: Refer to "Other Improvements Recommendations" for Pipe Insulation								
<input type="checkbox"/> Consider replacing system with high efficiency system of same type <input type="checkbox"/> Consider replacing with tankless system <input type="checkbox"/> Replace with high efficiency system at end of current systems useful life <input type="checkbox"/> Add Insulation Blanket <input type="checkbox"/>								
Comments: It is assessed that very little hot water is used in this building. Due to the plan to install geothermal, it is assumed that the geothermal system will provide the hot water. If this is not the case then it is recommended that a high efficiency tankless system be installed to provide hot water supply.								

Mechanical Ventilation Assessment						
System Type: <input type="checkbox"/> Exhaust <input type="checkbox"/> Balanced HRV		Manufacturer		Model Number	CFM	Hours of Operation
<input type="checkbox"/> Supply <input type="checkbox"/> Balanced ERV						
Distribution: <input type="checkbox"/> Connects to FHA <input type="checkbox"/> Dedicated Ducts						
System 1	Estimated System Efficiency					
	Estimated Age:					
System 2	Estimated System Efficiency:					
	Estimated Age:					
<input type="checkbox"/> System should be serviced <input type="checkbox"/> Additional Inspection is recommended by a HVAC technician <input type="checkbox"/> System over ventilates building <input type="checkbox"/> Consider replacement <input type="checkbox"/> System under ventilates building <input type="checkbox"/> Refer to Air Leakage Report for calculated flow rate <input type="checkbox"/> Monitor interior humidity trends and adjust run time accordingly <input type="checkbox"/>						
Comments: No ventilaiton system installed						


OTHER IMPROVEMENTS, RECOMMENDATIONS & CONSIDERATIONS

Item	Comments / Location	Recommendations	
<input checked="" type="checkbox"/> Hydronic Heating Pipes		Insulate with high quality / high R-value insulation	Estimated LF:
<input checked="" type="checkbox"/> Domestic Hot Water Pipes		Insulate with high quality / high R-value insulation	Estimated LF:
<input type="checkbox"/> Domestic Hot Water Tank		Add tank wrap insulation – follow manufacture's guidance	Tank Size:
<input type="checkbox"/> Low Flow Shower Heads		Install	Quantity: Color:
<input type="checkbox"/> Low Flow Aerators		Install	Quantity:
<input type="checkbox"/> Solar Hot Water System		Your site is conducive for solar hot water installation	
<input type="checkbox"/> Drain Waste Heat Recovery		Your plumbing configuration is conducive to a waste heat recovery system	
<input type="checkbox"/> Programmable Thermostats		Install and use setback when building is not occupied	Quantity: Type:
<input checked="" type="checkbox"/> Air Ducts – Leakage		Have all accessible ducts sealed (See Systems Report)	
<input checked="" type="checkbox"/> Air Ducts - Other	Ducts in Wall Cavities – Section A	Verify if ductwork is present or if wall cavity is used. Recommend completely removing ductwork from wall cavity and re-install inside the primary air barrier / thermal boundary.	
<input type="checkbox"/> Air Ducts – Insulation		Insulate all air ducts in non conditioned spaces to R9 or better (See Systems Report)	
<input type="checkbox"/> Lighting		Use compact florescent lighting to fullest extent possible	
<input type="checkbox"/> Lighting Controls		Automatic occupant sensing and shutoff switches are recommended	
<input checked="" type="checkbox"/> Phantom Electrical Loads		Use “smart” power strips for major items and turn off electrical devices at power strips at end of work day. Keep any items with AC/DC converter unplugged unless required for charging.	
<input type="checkbox"/> Attic Ventilation		Additional attic ventilation is recommended - Type:	
<input type="checkbox"/> Inefficient Freezer		Replace with an ENERGY STAR chest freezer appropriately sized	
<input type="checkbox"/> Kitchen Appliances		Replace with ENERGY STAR appliances at end of current appliances useful life	
<input type="checkbox"/> Laundry Appliances		Replace with ENERGY STAR appliances at end of current appliances useful life	
<input checked="" type="checkbox"/> Computers		Use the power save feature on your computers	
Additional Comments:			


HEALTH, SAFETY & BUILDING DURABILITY

Item		Comments	Recommendations
<input type="checkbox"/> Heating System – Emergency Service			Your Heating System Failed a Safety Check – Immediate Service is Required <input type="checkbox"/> CAZ Worst Case Depressurization <input type="checkbox"/> CO Spillage <input type="checkbox"/> Flue CO <input type="checkbox"/> Flue Draft
<input type="checkbox"/> Heating System – Service Past Due			Heating system is past due for service – recommend servicing
<input checked="" type="checkbox"/> Heating System – Annual Maintenance			Have heating system serviced annually by a qualified technician
<input checked="" type="checkbox"/> Combustion Appliance Zone (CAZ) Testing		Air sealing could impact draft of combustion appliances	Have CAZ testing accomplished upon completion or air sealing. Ensure carbon monoxide detector is installed in combustion appliance zone.
<input checked="" type="checkbox"/> Combustion / Make Up Air for Combustion Appliances			Ensure adequate combustion air is provided for all combustion appliances.
<input type="checkbox"/> Carbon Monoxide Detectors		<input type="checkbox"/> No Detectors Installed <input type="checkbox"/> Inadequate Quantity Installed <input type="checkbox"/> No CO Detector in CAZ	Install CO Detectors Per Code requirements Quantity Required:
<input type="checkbox"/> Smoke Detectors		<input type="checkbox"/> No Detectors Installed <input type="checkbox"/> Inadequate Quantity Installed <input type="checkbox"/> No Detector in CAZ	Install Smoke Detectors Per Code Requirements Quantity Required:
<input type="checkbox"/> Bath Fan & Venting	Fan Location Floor:	<input type="checkbox"/> No Fan Installed <input type="checkbox"/> Poor Quality Fan <input type="checkbox"/> Fan has Low Air Flow	<input type="checkbox"/> Recommend bath fan installation or replacement <input type="checkbox"/> Recommend time delay switch for fan control Type of fan recommended: _____ CFM Recommended: _____
	Ductwork Location	<input type="checkbox"/> Ductwork should be replaced <input type="checkbox"/> Ducts require insulation <input type="checkbox"/> Fan vents to attic space <input type="checkbox"/> Not able to inspect	All Bath Fans Must Vent to the Exterior Via Insulated Ducts Length of Duct Run: _____ <input type="checkbox"/> Exterior Vent is Required – Color: _____ Type of Vent Required: _____ <input type="checkbox"/> Wall <input type="checkbox"/> Roof <input type="checkbox"/> Use Insulated Flex Duct <input type="checkbox"/> Use Insulated Hard Pipe
<input type="checkbox"/> Sump pump pit			Moisture Sources Should Always be Mitigated Prior to Insulating or Air Sealing Cover sump pump pit with a cover that minimizes water vapor diffusion into basement area but would still allow water drainage from basement floor into pit in event of basement flooding. Alternative is to fit foil faced polyisocyanurate over pit to reduce vapor diffusion but constructed so polyisocyanurate will “float up” in event basement floods. Ensure discharge drains well away from structure.
<input type="checkbox"/> Wet or Damp Basement or Crawlspace Space 1 Location:		<input type="checkbox"/> Standing water present <input type="checkbox"/> Dampness observed <input type="checkbox"/> No vapor barrier installed <input type="checkbox"/> Exterior could not be observed <input type="checkbox"/> Owner reports space remains dry <input type="checkbox"/> Owner reports dampness	Moisture Sources Should Always be Mitigated Prior to Insulating or Air Sealing <input type="checkbox"/> Install 6 Mil or better vapor barrier over dirt floors and sealed to walls <input type="checkbox"/> Install gutters and drainage system that drains well away from structure <input type="checkbox"/> Install sump pump and drainage system that drains well away from structure <input type="checkbox"/> Install dehumidifier or exhaust ventilation controlled by humidistat <input type="checkbox"/> Improve exterior grading and drainage
<input checked="" type="checkbox"/> Humidity Levels			Monitor indoor humidity levels after air sealing and / or improvements to the thermal boundary. Average humidity should be below 60% in summer / 40% in winter.


SELECTED INFRARED IMAGES



2nd Floor Walls



2nd Floor Walls




2nd Floor Walls



2nd Floor – Section “C”

Uninsulated Foundation / Walls




1st Floor Section "A"





Uninsulated Slab



Insulated Walls- 1st Floor Section "C"




Uninsulated Foundation




Uninsulated Masonry




Air Leakage





Uninsulated Foundation / Wall



"Phantom" Electrical Loads



"Phantom" Electrical Loads



SELECTED DIGITAL IMAGES



Section "A" Attic



Wall Between Conditioned Space and Attic

Defective Air Barrier



Section "C" Attic

Defective Air Barrier



Uninsulated Hatch - Section "C"

Inadequate Air Barrier / Holes in Air Barrier

Metal Ceiling

Inadequate Air Barrier



Uninsulated Foundation / Slab

Unused Low R-Value / Leaky Door